

**CITY of
SPRINGFIELD**



August 19, 1991

Ms. Felicia L. Pfeffer, Project Manager
Riedel Environmental Services, Inc.
5233 North Pearl Street
Rosemont, Illinois 60018

Re: 1611 North Campbell

Dear Ms. Pfeffer:

Per your request dated August 15, 1991, the enclosed copies of letters and memos, plus a portion of our sanitary sewer wye location map comprise our references to the gasoline problem in the area of 1611 North Campbell.

This office has received many complaints and conducted numerous investigations of gasoline in the sanitary sewer in this area. No source has ever been confirmed.

Concerning the 1611 North Campbell address, this office did conduct a site investigation at that location during the continuing investigation and did not find a source for our vapor problem. No written record of that investigation was made.

If you have any questions please feel free to call 417-864-1924.

Yours truly,

Stephen Short
Water Pollution Control Inspector

Enclosures

cc Robert Schaefer, P.E., Supt. of Sanitary Services
Steve Meyer, P.E., Sanitary Engineer
Randy Lyman, Sewer Surveillance and Billing Supervisor
file

1611 N. CAMPBELL



RIEDEL ENVIRONMENTAL
SERVICES INC

August 15, 1991


Randy Lyman
Sanitary Service
Springfield City Hall
1216 W. Nichols St.
Springfield, MO 65802

Dear Mr. Lyman;

In accordance with the Freedom of Information Act, Riedel Environmental Services is requesting any information concerning the presence of gasoline and/or vapors in the sanitary sewers near Phillips Machinery, 1611 N. Campbell, Springfield, Missouri. Any information you have pertaining to City Utilities (1600, 1602, and 1606 North Campbell) would also be appreciated.

It was a pleasure speaking to you this morning. If your department discovers any new occurrences in the area, please call. Thank you for your assistance in this matter.

Sincerely,
RIEDEL ENVIRONMENTAL SERVICES INC.


Felicia L. Pfeffer
Project Manager

FLP/dmc

